



## EARTH LEAKAGE RELAY HARDWARE UPDATE

### WHAT HAS CHANGED

Some of the relays components are experiencing obsolescence issues, and have been updated to ensure continued production.

New item numbers for the current discrete Earth Leakage Relays have been allocated to facilitate these changes. The functionality, form and fitment of these relays remains unchanged

### PRODUCT COMPARISON

Existing Relay	Existing Item Number	Replacement Relay	Replacement Item Number
ELD V1	101567	ELD V3 EXTD TRIP*	179722
ELD V2	115161	ELD V3	167259
ELD V2 NO CT TRIP	121773	ELD V3 NO CT TRIP**	179721
ELM	121398	ELM V2	179723

\*The ELD V3 EXTD TRIP – Has Extended Trip Time settings and a non-fail-safe operation (non-compliant to AS2081-2011)

\*\*The ELD V3 NO CT TRIP - Has the CT monitoring & trip function disabled (non-compliant to AS2081-2011)

### WHAT DO I NEED TO DO

Please use the “replacement item number” when ordering new product / update your engineering & procurement database system accordingly

### TIMING

Replacement item number versions will be phased in during July & August 2018. Original item number versions will continue to be sold until stock is exhausted.

### FIND OUT MORE

For more information on this product, please contact Ampcontrol Customer Service on +61 1300 267 373 or [customerservice@ampcontrolgroup.com](mailto:customerservice@ampcontrolgroup.com) or visit the Ampcontrol website: [www.ampcontrolgroup.com](http://www.ampcontrolgroup.com)

### DISCLAIMER

While every effort has been made to ensure the accuracy of this document at the date of issue, Ampcontrol assumes no liability resulting from any omissions or errors in this document, and reserves the right to revise content at any time.